Certificate of Location of Government Corner

ID#: 512106 **Description:** 1/4 SEC COR 20 21 51 **Date Set:** 1/9/2013 **County:** Olmsted

Section: 21 **Township:** 105N **Range:** 11W **Monument Description:** Cast Iron Cap on Telspar Pipe

Reference Ties:

The monument is up 0.2'
The corner falls 2' east of N-S fence and 1' north of E-W fence
Sign on east side of corner post
This corner is located by GPS reference stations "Hanson A & B"

Corner History:

Gov't notes: set 1/4-sec-post, 40 chs. 5" Burr Oak S75-1/2ºW, 95 lks. 4" Burr Oak S56-1/2ºE, 65 lks.

4-25-1878 T. Hunter (Book A, Pg 338 No 332) Section 21 corner missing and BTs gone. But Mr. Gardner avered that corner 4-way-fences exactly where original corner lay. Used corner post as corner.

6-9-1899 W. Fraser (Field Book 9 Pg 41-42) drawing of plat shows apparent BT: N14-1/2ºE, 12" Cottonwood, 49 lks.

7-6-1976 County Surveyor shot corner post and used for Right of Way Plat No. 4

4-27-2007 County survey crew visited area and found nothing.

1-9-2013 County Surveyor decided to accept the 1976 fence corner post location as the corner. County survey crew set 5' telspar pipe with cast iron cap at the 1976 corner post location.