Certificate of Location of Government Corner

ID#: 512209 **Description:** SEC CEN 22 51 **Date Set:** 11/30/2012 **County:** Olmsted

Section: 22 **Township:** 105N **Range:** 11W **Monument Description:** Note: Information regarding this center of section is provided for reference purposes only. A professional land surveyor should make the decision whether to use any existing survey monument or the computed intersection of quarter lines.

1/2" pipe w/cap RLS #8952

Reference Ties:

The corner falls 2' east of N-S fence and 1/2' south of E-W fence
The monument is up 0.1'
This corner is located by GPS measurement

Corner History:

6-18-1873 Thomas Hunter, County Surveyor, (Book A, Pages 230-231, Survey No. 233) set stake at intersecting quarter lines. 1/16th North set stake midway and on line at 20.07-1/2 chains (1324.95') to North 1/4. 1/16th South set stake midway and on line at 20.13-1/2 chains (1328.91') to South 1/4. 1/16th East set stake midway and on line at 19.94 chains (1316.04') to East 1/4. 1/16th Center of NE 1/4 set stake at intersecting sixteenth lines. 1/16th Center of SE 1/4 set stake at intersecting sixteenth lines.

4-22-1878 Thomas Hunter, County Surveyor, (Field Book #5, Page 56) found stake. 1/16th North set stake. 1/16th East found stake.

7-11-1976 County Surveyor dug and probed and found nothing.

9-2-1997 GGG used computed center at intersecting quarter lines.

11-13-2012 Joel Thoreson, County Surveyor, recommends using the computed intersection of quarter lines for the center of section.

11-30-2012 Roger Brand & Associates set 1/2" pipe with cap at intersecting quarter lines.

12-27-2012 County Survey Crew found 1/2" pipe with cap up 0.1' in good condition and measured its position using GPS. Based on the county's section breakdown, the 1/2" pipe w/cap, as located by GPS in 2012, falls 0.20' south and 0.04' east of the computed center.

10-23-2015 Massey Land Surveying found and used 1/2" pipe w/cap at intersecting quarter lines.