Certificate of Location of Government Corner

ID#:512804 **Description:** 1/4 SEC COR 28 33 51 **Date Set:** 8/7/2006 **County:** Olmsted

Section: 28 **Township:** 105N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 1' east of the main line of fence south, 4' east of fence north and 8 1/2' south of centerline of E-W twp road on curve
County Survey Disk in PP #2383 ESE 74.84'
This corner is located by GPS measurement

Corner History:

Gov't notes: Set 1/4-sec-post. 8" Burr Oak, S57-1/2 ºW 67 lks 10" Burr Oak, N56 ºW 144 lks [Corner in road on high table land, very near to descent into ravine.]

4-1878 T. Hunter pg 337 no 331 corner gone. NW BT standing [10" Burr Oak, N56 ºW 144 lks]. Mr Ed Suohy avers he set fence south in line and 2 rods south which checked with BT. Set stone 3 x 3/9 x 21" at joint. Measure W 39.93 chs, Measure E 39.87 chs

[See T.Hunter Bk 5 pg 60 sec 33]

7-3-1985 County Surveyor dug for Hunter's corner. Found stone down 3.5' knocked and broken, but base still in place and dug well into clay. Drove 1" square pipe at stone location and stood stone on S side.

7-8-1985 County Surveyor set a CIM over a 0.5x12" iron as the corner over the stone location. 1/16 E - Dug but found nothing.

8-7-2006 County Surveyor found CIM down 1.0' in good condition, took local ties and removed. Found iron rod down 2.6', took local ties and removed. Set 3' telspar w/CIC down 0.5' from local ties taken from CIM. CSD w/nail in south of PP # ESE 74.84', tie in corner post gone.

4-30-2007 County Surveyor found telspar pipe w/CIC down 0.5' in good condition.