Certificate of Location of Government Corner

ID#:512805 **Description:** SEC COR 28 29 32 33 51 **Date Set:** 9/9/1975 **County:** Olmsted

Section: 28 **Township:** 105N **Range:** 11W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 2' east of fence south and 1 1/2' south of fence west
County Survey Disk in SW side 36" Elm NW 95.3'
County Survey Disk in NE side CP NW 2.41'
Sign on CP 2 1/2' NW
This corner is located by GPS measurement

Corner History:

9-1853 Gov't Notes W.A. Jones, Deputy Surveyor North between sections 32 and 33. 80.00 chs. Set post corner to section 28,29,32 and 33. Burr Oak 8 in. S78W 164 lks. Burr Oak 7 in. N611/2E 92 lks. Burr Oak 6 in. S42E 82 lks. Burr Oak 9 in. N321/2W 225 lks.

4-1878 Thomas Hunter (P. 337 No. 331), County Surveyor, found original stake lying on ground plowed out. Found remains of lower part below plowing. Set stone 2"x5"x15" (deep) with 2"x14"x22" stone on top.

4-1878 Thomas Hunter (P. 341 No. 335) found stone P. 337.

1932 John Kerr (B. 12 P. 51), County Surveyor, found stone in place as recorded. Reset 2"x19"x22" stone on top.

9-9-1975 County Surveyor found 11/2"x20"x22" stone over 2"x5"x15" stone. Removed stones and set C.I.M. over 3/4"x15" rod as corner. Set 2"x5"x15" stone on W. side of C.I.M. and 11/2"x20"x22" stone on N. side (up 6").

7-30-1985 County Surveyor CIM is now 2' east of fence south and 1-1/2' south of fence west.

2-10-2005 County Surveyor found CIM in good condition down 0.3'. CSD w/nail in NE side of corner post NW 2.41'. Did not check tie to Elm.