Certificate of Location of Government Corner

ID#:513004 **Description:** 1/4 SEC COR 30 31 51 **Date Set:** 8/28/2003 **County:** Olmsted

Section: 30 **Township:** 105N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 4' south of E-W fence and in line with fence south
County Survey Disk in 12" Aspen SE 5.16'
County highway disk in 30" Oak (up 2') SW 58.58'
Post with sign 2' NW
This corner is located by GPS reference stations "French A & B"

Corner History:

Gov't notes: Set 1/4-post and stone 24x15x2". Dug trench . 10" Burr Oak, N86-1/2ºW 899 lks

5-1901 W.Fraser pg 12 B sec 31 found corner gone. NWBT standing but too far away to set corner alone. Run line set stake at intersecting North section line where measure from BT intersected (???). Measure West 39.77 chs, East 40.09-3/4 chs.

1969 Sankstone set 0.5x30"-corner-rod and took new ties. Subdivided ..... of old records .....

6-1973 Sankstone and Taylor found rod of 1969. Measured E.T.C. - East 2645.62', South 2631.21'.

7-13-1977 Mn/DOT Survey Crew took R.P.'s to 0.5" rod 4' South of E-W fence and in fence South.

4-11-1991 County Surveyor found 1/2" rod in good condition.

8-28-2003 County Surveyor found 1/2" rod down 0.1'. Took local ties and set CIC on 4.0' telspar pipe over rod up 0.4'.

2-11-2005 County Surveyor found CIC in good condition up 0.4'