Certificate of Location of Government Corner

ID#: 513204 **Description:** S 1/4 SEC COR 32 51 **Date Set:** 9/4/2003 **County:** Olmsted

Section: 32 **Township:** 105N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls in SE corner of property lot for house #11952
3/4" rod S 230.0'
5/8" rod SW 234.59'
Post with sign 6' east
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes West on south boundary of section 32. 40.00 chs. Set quarter section post. Burr Oak 6 in. N78W 62 lks. Burr Oak N75E 5 in. 191/2 lks.

4-1878 Thomas Hunter (P. 341 No. 335), County Surveyor, found stump of N.W. bearing tree which placed corner at corner post of fence running south-accepted post as corner.

12-1886 Thomas Hunter (P. 418 No. 407) found corner P. 341. Set new stake.

3-1938 John Kerr (B. 12 P. 51), County Surveyor, found iron bar in a pile of stone in field.

9-10-1975 Dave Knutson, Filmore County Surveyor, found iron bar in cultivated field. Fillmore County Certificate of Location Doc. No. 372132

9-10-1975 Olmsted County Surveyor found a 1" square shaft in cultivated field and accepted as corner.

9-4-2003 Olmsted County Surveyor found 3/4" pipe property pin up 2.0'. Removed and found 1" square shaft down 1.3'. Took local ties and removed shaft. Set CIC on 6' telspar pipe down 0.3'.

2-9-2005 Olmsted County Surveyor found telspar pipe w/CIC down 0.2'