Certificate of Location of Government Corner

ID#: 513305 **Description:** S SEC COR 32 33 51 **Date Set:** 2/23/2005 **County:** Olmsted

Section: 33 **Township:** 105N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

County Survey Disk in N side 6" Elm E 10.60'
County Survey Disk in W side blazed 5" Elm SW 15.22'
County Survey Disk in E side blazed 6" Burr Oak NE 49.22'
Post w/sign 2' south
This corner is located by GPS reference stations "Snyder A & B"

Corner History:

9-1853 Gov't Notes: Set post for corner. Bearing Trees Burr Oak 10" S60ºW 86 lks. Burr Oak 5" N82ºE 263 lks.

4-1878 T. Hunter P. 341 No. 335 Found original corner also both Bearing trees standing. 1/16 north set stake M&L 20.011/2 to 1/4 cor. set M&L.

12-1886 T. Hunter P. 418 No. 407 Found original corner standing P. 341. Original Bearing Tree: 5" Burr Oak N82ºE 263 lks. 10" Burr Oak S60ºW 86 lks. 1/16 west set stake marked M&L 20.01.

9-15-1975 Olmsted County Surveyor could find no evidence of corner. Set 3/4"x24" iron with nut on top down 8" as corner by doubling line and measure from Sec. Cor. 28-29-32-33 over 1/4 Cor. 32-33. Left angle iron up as witness.

8-14-1985 Olmsted County Surveyor found bolt set with iron guard. R.P.'s okay but Elm dying.

8-15-1985 Olmsted County Surveyor found no more. Set short 3/4" rod at stone location and covered with limestone and laid huge stone found over all. Look west of stone for corner post which would improve bearing and distance to stump. Stone N55º30'E (mag), 21.0 from bolt or appx. 171/2' E and 101/2 N. of bolt by Magnetic bearings.

10-31-1989 Doug Rude, Yaggy Colby Associates, found 3/4" iron with bolt on top. Fillmore County Certificate of Location Doc. No. 372131

2-23-2005 Olmsted County Surveyor set 4' telspar w/CIC over 3/4"x24" iron. CSD in north side up 4.0' in 8" Elm SW 15.22', CSD in north side up 2.5' of 6" Elm east 10.60'. Did find spike in 6" Burr Oak NE 49.22'. All other ties gone. Set sign and post 2.0' south.