Certificate of Location of Government Corner

ID#:513306 **Description:** 1/4 SEC COR 32 33 51 **Date Set:** 9/1/1975 **County:** Olmsted

Section: 33 **Township:** 105N **Range:** 11W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 3' north of fence east
Post w/sign 2' south
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes W.A. Jones, Deputy Surveyor North between sections 32 and 33. 40.00 chs. Set quarter section post. Burr Oak 10 in. N41W 190 lks. Burr Oak 12 in. N8E 835 lks.

4-1989 Thomas Hunter (p. 341 No. 335), County Surveyor states corner gone and in open field. Set stone with stake by side midway and on line as corner.

1936 county highway department (B. 81 P. 37) found limestone by fence corner.

9-1-1975 County Surveyor found pointed limestone standing up and partially out of ground. Accepted as corner location after digging and set C.I.M. over rod.

7-31-1985 County Surveyor at 1/16 east dug from t.n. (set in centerline road and in line fence west) for 1/2' west, 6-1/2' east, 3' north, and 5' south by 1-1/2' deep to clay. Found nothing. Road in cut on west side. Not very good condition line to post hole found at the 1/16 east of the center 33 came 2.7 south of t.n. and full meas from 1/4 cor 32-33 came 3.73 east.

8-13-1985 County Surveyor at 1/16 south traversed into old fence corner to fences west and south. Dug around and found post hole. Post hole 4.3 north and 10.5 east of cole 1/16 between present corner.

2-18-2005 County Surveyor found CIM down 0.6' in good condition. Set post w/sign.

4-3-2007 County Surveyor found CIM down 0.6' in good condition.