Certificate of Location of Government Corner

ID#:520405 **Description:** SEC COR 4 5 8 9 52 **Date Set:** 6/4/2009 **County:** Olmsted

Section: 04 **Township:** 105N **Range:** 12W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The monument is down 0.3'
The corner falls 12' east of centerline of CR 129 and 27' north of centerline of twp road west
County Survey Disk in SW side PP NNW 46.23'
Bottle cap in NW side PP #16558 SW 68.82'
SW corner main house NNE 170.9'
This corner is located by GPS measurement

Corner History:

10-6-1853 Gov't Notes William Jones 80.00 chs. Set post corner to sect. 4-5-8-9 Red Oak 6 S 19 W 223 Burr Oak 10 S 131/2 E Burr Oak 7 N 43 E 202 Set charred stake & made trench

1879 Thomas Hunter Book #5 page 94 - Survey Section 8.

6-1891 Thomas Fraser P. 452 No. 436 S8 James Campion could not find corner.

7-1968 J. Kerr set 120 D 2' North mail box 1.0' from east edge N-S road in line center road west to meas. South. Record 2640.2' to 1/4 section corner so. Or 5280.4'. Actual 5251.3' to stone found at 8-9-16-17 indicating road W too far so.

8-5-1968 J. Kerr set 1/2"x3' rod as corner 5280.3' no. of SE8'and 5268' east of NW 8' as per records. Rod comes 29' north center road west - 5' east of east edge traveled road north. 71.8' SW to center no plate on power pole.

9-23-1968 J. Kerr set corner CIM after running 2 miles & meas. Did not dig. SW corner main house NNE170.9' Disc in power pole 16 553' SW 68.9' Corner lies 3' east of east edge traveled N-S road. Corner lies about 27.0' north center road west. Corner lies about 2638'. To NW1/4 & W1/4 9.

11-18-1998 County Surveyor found CIM in good condition down 1.2' on East edge of CR 129.

5-4-2009 County survey crew found CIM down 1.4' in good condition.

6-4-2009 County survey crew found CIM down 1.4' in good condition. Took ties and removed. Found 3/4" x 2' pipe down 3.2' in good condition. Set 5' telspar pipe w/CIC down 0.4' at CIM location.

2-24-2011 County survey crew found CIC on Telspar pipe in good condition.