Certificate of Location of Government Corner

ID#:520406 **Description:** 1/4 SEC COR 4 5 52 **Date Set:** 6/2/2009 **County:** Olmsted

Section: 04 **Township:** 105N **Range:** 12W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The monument is down 0.3'
The corner falls 20' east of centerline of CR 129, 10' south of centerline of field entrance east, in line with fence east and 2 1/2' north of fence west.
Post with sign, east 2'
This corner is located by GPS measurement

Corner History:

10-6-1853 Gov't Notes South on true line between sections 4 & 5 course south. 38.53' set qr. Section post. 78.53' Sec. corner.

6-1891 Thomas Fraser P. 452 No. 436 found stone 4" x 6" square on top used in setting SE corner 8 and E 1/4 corner 8 on 2 mile measure which overran .8' in 2 mi. - did not run line.

8-1968 J. Kerr dug twice for corner from center road east over 15'. Set 1/2" x 2' rod on section line from NW 4 to rod set as SW 4 and above chainage. Rod comes 2 to 3' north fence east & 8 to 10' east of east edge road. 7.6' to center TP SE 10.4' to center corner fence post ESE 19.0' to center corner fence post NE.

9-20-1968 J. Kerr dug, found nothing. Set CIM on line a proportional distances for 2 mi. Corner lies 19' E of center N-S road. Corner lies on line fence E. - 2 1/2' S to fence running W. Hard nail in CP east 11.15'. Hard nail in CP NE 22.3' Disc in PP SE 6.4'. Cap in fence post 2.5' S & W 54.05'.

5-4-2009 County survey crew found CIM down 1.9' in good condition.

6-2-2009 County survey crew removed CIM and found 1/2" rerod down 3.5' in good condition. Removed 1/2" rerod and set 6' telspar pipe w/Cast Iron Cap down 0.3' at CIM position.

10-18-2010 County survey crew found CIC in good condition