Certificate of Location of Government Corner

ID#:520605 **Description:** W SEC COR 6 7 52 **Date Set:** 10/15/2004 **County:** Olmsted

Section: 06 **Township:** 105N **Range:** 12W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 25' south of centerline of field drive
Post with sign 15' north
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes Ball, Deputy Surveyor North between sections 7 and 12. 80.00 chs. Set corner post. Dug trench and planted osage orange S.E. and apple seed N.E. Burr Oak 8 in. N48ºE 64 lks. Burr Oak 10 in. N41ºW 322 lks.

10-1853 Gov't Notes William A. Jones, Deputy Surveyor Measured south on west side section 7. Find length of mile only 79.10 and find that corner to sections 7, 12,13,18 and to 1,6,7,12 have been established south of original measurement.

12-1875 Thomas Hunter, County Surveyor, (Field Book 4 P. 86-87) measured North 80.01 chs. To the N.W. Cor. Sec. 6 and set the W. 1/4 Cor. Sec. 6 midway and on line.

7-1876 Thomas Hunter (P. 301 No. 296 and Field Book 4 P. 142-145) found the original stake and tested it with the N.W. bearing tree still standing. Set a stake at the 1/16th West midway and on line to 1/4 Cor. 1-12.

7-1876 T. Hunter (P. 302 No. 297 and Field Book 4 P. 142-145) set a stake at the 1/16th East on line and at proportionate Gov't measure. Measured East 79.22 chs. (5228.52'). Found stake at 1/4 Cor. 6-7.

7-1969 John Kerr, County Surveyor, (B. 101 P. 4) set a C.I.M. as the corner at double the measure from the N.W. Cor. Sec. 6 over the E-W fence at the W. 1/4 Cor. Sec. 6 and at 5229.6' from Sec. Cor. 5-6-7-8.

4-22-1977 County Surveyor found a stake at the 1/16th East. Doubled the line and prorated Hunter measure from 1/4 Cor. 6-7 over the stake found and dug for the corner. This point came approx. 8' East and 9' South of Kerr's corner. Dug from this point West 9', North 6', and South 4'. Could not find the corner; however, found much old fence wire running E-W approx 2' South of this point.

The correct corner is 9.16' south and 2.40' East of Kerr's C.I.M. (removed).

4-26-1977 County Surveyor set a C.I.M. as the corner on line from 1/4 Cor. 6-7 (found) over the stake found at the 1/16 West and at the prorated Hunter measure from 1/4 Cor. 1-12 (found) to 1/4 Cor. 6-7. This location also came on the line from 1/4 Cor. 1-12 over the fence at the 1/16th East. The corner is 9.16' South and 2.40' East of Kerr's corner (removed).

10-15-2004 County Surveyor found CIM down 0.2' with head broken off. Took local ties and removed. Found 1/2" rod down 2.0'. Set 7' telspar pipe w/cast iron cap down 1.7'.