Certificate of Location of Government Corner

ID#:520606 **Description:** W 1/4 SEC COR 6 52 **Date Set:** 4/27/1977 **County:** Olmsted

Section: 06 **Township:** 105N **Range:** 12W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 4 1/2' south of E-W fence and 37' east of fence south
SW corner of cement corner post (1' from top) WNW 37.38'
County Survey Disk in S side brace post SW 39.00'
Post with sign 2' north
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes John Ball, Deputy Surveyor North between sections 1 and 6. 40.00 chs. Set quarter post. Burr Oak 10 in. S60ºW 20 lks. Burr Oak 10 in. S68ºW 10 lks.

12-1875 Thomas Hunter, County Surveyor, (Field Book 4 P. 87) states that the stake was gone. Set the corner midway and on line between the section corners.

7-1876 T. Hunter (P. 301 No. 296 and Field Book 4 P. 143) found the stake set midway and on line.

7-1876 T. Hunter (P. 302 No. 297 and Field Book 4 P. 145) states that the corner was set midway and on line.

5-1880 John Fraser (P. 365 No. 356) states that the corner was gone. A Mr. Predmore and a Mr. John Campion showed him a stone they said was set by Hunter which he later found to be wrong (21/2 rods too far West) after studying the records.

4-26&27-1977 County Surveyor dug 7'x7' at the midway and on line location but did not find anything. Set a Cast Iron Cap on a square pipe as the corner midway and on line between the section corners. The corner is 41/2' south of the E-W fence and 37' East of the fence South.

10-15-2004 County Surveyor found cast iron cap on telspar pipe down 0.8' in good condition.