Certificate of Location of Government Corner

ID#:520804 **Description:** 1/4 SEC COR 8 17 52 **Date Set:** 4/28/1977 **County:** Olmsted

Section: 08 **Township:** 105N **Range:** 12W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The monument is down 0.2'
The corner falls 6' south of CP to fences E-W-N
This corner is located by GPS measurement.

Corner History:

10-1853 Gov't Notes William A. Jones, Deputy Surveyor West on true line between sections 8 and 17. 40.00 chs. Set quarter section post. Burr Oak 11 in. N65ºW 214 lks. Burr Oak 4 in. S411/2ºE 134 lks. 80.00 chs. To section corner.

3-1879 Thomas Hunter, County Surveyor, (Field Book 5 P. 94) states that the 1/4 post was missing, but he found fences running N-S, a fence running West, and the stump of a bearing tree putting the corner at the intersection of the fences.

6-1891 Thomas Fraser, County Surveyor, (P. 452 No. 436) states that the corner was gone. Set the corner midway and on line between the section corners.

6-1902 Robert Fraser, County Surveyor, (P. 710 No. 624) found a limestone set in a former survey.

4-1977 County Surveyor found a 11/2"x5"x18" limestone underneath a large Boxelder tree. The corner came midway and on line between the section corners.

4-28-1977 County Surveyor set a Cast Iron Cap on a square pipe as the corner with the stone on the West side.

2-28-2011 County survey crew found CIC in good condition.