Certificate of Location of Government Corner

ID#:520806 **Description:** 1/4 SEC COR 7 8 52 **Date Set:** 3/31/1977 **County:** Olmsted

Section: 08 **Township:** 105N **Range:** 12W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 3 1/2' east of centerline of N-S twp road and 1 1/2' south of fence west
County Survey Disk in N side (up 5') 17" blazed Burr Oak WNW 44.88'
Spike in N side 17" Pine ESE 67.20'
Punch hole in S end CMP SE 36.38'
County Survey Disk in PP #41216 SW 128.33'
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes William A. Jones, Deputy Surveyor North between sections 7 and 8. 40.00 chs. Set post at the quarter section corner. Burr Oak 6" N11/4ºE 55 lks. Burr Oak 6" S34ºW 78 lks.

11-1877 Thomas Hunter, County Surveyor, (P. 325 No. 319) could not find the corner. Set a stone as the corner midway and on line between the section corner.

6-1890 Thomas Fraser, County Surveyor, (P. 452 No. 436) found the stone set by Hunter P. 325. Set stones at the 1/16th East and the Center 8.

4-1909 Charles Armstrong, County Surveyor, (P. 116B) found the recorded stone.

4-28-1968 John Kerr, County Surveyor, (B. 100 P. 1-2) found the Center 8 and a stone at the 1/16th West. Doubled the line and measure from the Center 8 over the stone found at the 1/16th West and set a 1/2" rod as the corner. The corner came in a culvert of a farm driveway.

6-25-1968 John Kerr (B. 100 P. 1-2) dug for the corner and found the recorded stone 10.0' West of the rod set 4-28-1968. Lowered the stone and set a CIM over it.

3-31-1977 County Surveyor dug down to Kerr's CIM. Set a CIM over it and up to the surface of the road.

10-18-2004 County Surveyor found CIM down 0.6' in good condition.