Certificate of Location of Government Corner

ID#:520905 **Description:** SEC COR 8 9 16 17 52 **Date Set:** 7/3/1968 **County:** Olmsted

Section: 09 **Township:** 105N **Range:** 12W **Monument Description:** Cast Iron Monument

Reference Ties:

The monument is down 0.6'.
The corner falls 2' north of fence east, 1/2' east of centerline of CR 129, 19' north of centerline of field entrance east and 31 1/2' north of centerline of field entrance west.
This corner is located by GPS measurement.

Corner History:

10-6-1853 Gov't. Notes William Jones 80.00 chs. Set post corner to sections 8-9-16-17 Burr Oak 5N31W 45 Red Oak 7N7E 23 And dug trench.

6-1891 Thomas Fraser P. 452 No. 436 corner gone - Set stone 20"x2"x8/15" as follows: Measure 1/4 16-17 (marked stake) No. to 1/4 4-5 (stone in road 4"x6" top) overran 10" set at 2640.2. Measure SW 8 to SE 9 - Set stone at prop. Gov't measure as south line 8 recorded as 2640 and south line 9 as 2643 each half.

6-1902 R. Fraser P. 710 No. 624 Found limestone set P. 452 in line fence running east. 1/16 West set stake 20.01' M&L. 1/16 South set stake 19.991/8 M&L.

7-3-1968 J. Kerr to relocate corner. Meas. Line from 1/4 4-5 fence east to sec. Line fence east total .5' short of full 11/2 miles. Set 120d in center road west at 4-5-8-9 2' south of mail box about 1' from east edge of traveled road. This too far so. 2666.5' north to fence east. From 120d south to sect. Corner found 52.51.3' archived record for 2 miles 2640.2' which indicates road west way south of true location. No corner ever set there. Found recorded limestone with stones on 4 sides. Set rash weight on each side with CIM down 8" on top. Corner lies 2.0' north fence east very near center road N-S. Disc in corner post 2' south of each 35.0'. Disc in new cedar 4' south of W 35.0'. Southeast corner old shed SW 52.5'.

12-8-1998 County Surveyor found CIM down 0.8' in good condition.

6-1-2009 County survey crew found CIM down 0.6' in good condition.

2-24-2011 County survey crew found CIM in good condition.