Certificate of Location of Government Corner

ID#:520906 **Description:** 1/4 SEC COR 8 9 52 **Date Set:** 5/5/2009 **County:** Olmsted

Section: 06 **Township:** 105N **Range:** 12W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 8 1/2' east of centerline of CR 129, in line with fence west and 75' south of centerline of field entrance west
This corner is located by GPS measurement

Corner History:

10-6-1853 Gov't Notes North between sections 8&9 Var 10º 18'E 40.00 Set qr. Section post. Burr Oak 7N 35W 86 Burr Oak 5S 14E 118

3-1879 Tom Hunter Survey Book #5 Page 94 Unrecorded survey of section 8 corner set M&L 39.97'.

6-1891 Thomas Fraser P. 452 No. 436 no corner in evidence. 1/4 the distance from 1/4 16-17 to 1/4 4-5 (a stone) 26401/2 E.K. (recorded stake).

9-23-1968 J. Kerr set CIM on 2 mile section line and porportionate distance. Did not dig for corner common land both sides.

12-8-1998 County Surveyor found CIM down 1' in good condition in crushed rock CR 129.

5-5-2009 County Surveyor found CIM down 1.1' with slight lean east. Removed CIM and found 1/2" rerod down 2.7' in good condition. Set 4' telspar pipe w/Cast Iron Cap down 0.4' at 1/2" rerod position.