Certificate of Location of Government Corner

ID#: 521004 **Description:** 1/4 SEC COR 10 15 52 **Date Set:** 4-24-2018 **County:** Olmsted

Section: 10 **Township:** 105N **Range:** 12W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 25' south of corner post for fences north and east
The monument is down 1.5'
Sign on corner post 25' north
This corner is located by GPS reference stations "Startled A & B"

Corner History:

10-6-1853 Gov. Notes West on true line between section 10&15 VAR 9º23-E. 40.06' Set qr. Section post. Stone in mound 10"x6"x2" 80.12' To section corner.

5-7-1903 C. Armstrong, County Surveyor, Book B, Page 50, Measured from SE Section Corner 10 west 40.02 chains (2641.32') to 1/4 Corner 10-15.

7-16-1962 J. Kerr, County Surveyor, Book 85, Page 60, Ran north line Section 15 found clutch small stones at M&L set CIM 2626.5' east nearly same west - rough country. RPs - Center twin Burr Oaks N01°30'E 53.1'

3-31-1980 County Surveyor visited corner and found Cast Iron Monument cemented in on north side of large 4" pipe post and 25' south of line running east.

12-14-2007 County Survey Crew found Cast Iron Monument at surface in good condition and measured its position using GPS.

10-24-2017 County Survey Crew visited area of corner. Area is now in a plowed field. Found nothing.

4-24-2018 County Survey Crew set 5' telspar pipe with Cast Iron Cap at previously GPS location down 1.5' in plowed field.