Certificate of Location of Government Corner

ID#:521206 **Description:** 1/4 SEC COR 11 12 52 **Date Set:** 12/21/1998 **County:** Olmsted

Section: 12 **Township:** 105N **Range:** 12W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The monument is down 1.4'
The corner falls 28' west of field division and 75' NE of centerline of field waterway
This corner is located by GPS measurement

Corner History:

10-6-1853 Gov't Notes No. between Sects. 11 & 12 VAR 10°E 3.00 Dry bed of brook 6 lks. wide runs S.W. 26.00 Top of Bluff 40.00 Set qr. sect. post Br. Oak 7S2E 485 lks. 7" S2°E Br. Oak 6N3W 316 lks. 6" N3°W 79.30 Brook 5 lks. wide runs S.E.

2-1867 H. Horton P. 83 No. 123 1/16 No - 20.00 M&L - N1°33'W - S45°W 24 lks. 1/16 E - 19.94 M&L - S89°15'W - S20°W 67 lks. 1/16 So - 20.04 M&L - N1°14'W - N66°E 60 lks. N70°W 50 lks.

2-1877 T. Hunter P. 311 No. 302 Corner came in open culv. field all B trees gone. Set temp. stake 40.15 1/2 M&L. N1°W 1/16 No. set stone 2"x10"x37" M&L N1°W 20.07 3/4 lks. 1/16 So. set temp stake 20.07 3/4 M&L N1°W

5-1903 C. Armstrong P. 50 B Likely didn't establish corner. 1/16 So. set corner M&L 20.06 lks. 1/16 No. found stone set by Hunter P. 311.

12-21-1998 County Surveyor set Cast Iron Cap on telspar pipe down 1.7' midway and on line between section corners at position used by Hunter and Armstrong.

3-21-2011 County survey crew found CIC in good condition