Certificate of Location of Government Corner

ID#: 521704 **Description:** 1/4 SEC COR 17 20 52 **Date Set:** 7/28/2011 **County:** Olmsted

Section: 17 **Township:** 105N **Range:** 12W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The monument is down 0.9'
The corner falls under E-W fence
County Survey Disk in S side wood fence post W 15.85'

Corner History:

10-1853 Gov't Notes William A. Jones, Deputy Surveyor West on true line between sections 17 and 20. 40.045 chs. Set quarter section post. Maple 14 in. N87ºE 30 lks. Elm 14 in. S75ºW 35 lks. 80.09 chs. To section corner.

6-1857 Thomas Hunter (P. 32 No. 50), County Surveyor, used this corner.

6-1902 Robert Fraser (P. 710 No. 624 and old Field Book 10 P. 47) County Surveyor, found a stone at the corner as put in a former survey (no description of the survey or corner given). Set a limestone at the 1/16th East midway and on line.

4-1905 Robert Fraser (P. 80B) found a stone and stake set in a former survey and found P. 710. Set a stake 3.73' & 5/6 chs. West as a property corner.

4-1977 County Surveyor found a 11/2"x7"x21" limestone lying on its side with a 1/2"x43" pipe along side under the E-W fence. Found the stone set by Robert Fraser at the 1/16th East in Survey No. 624. Found a 3/4"x11/2"x3' iron at the property corner set by Robert Fraser 3.73 & 5/8 chs. West of the corner in the Survey P. 80B. Set a Cast Iron Cap on a 4' long square pipe as the corner on line from Section Corner 16-17-20-21 over the 1/16th West (found) and at Robert Fraser's measure East of the iron found at the property corner West. The corner came at the location of the stone and pipe found. Set the stone on the North side of the CIC.

2-23-2011 County survey crew found CIC on telspar pipe leaning south.

7-18-2011 County survey crew found cast iron cap on square pipe at the 1/16th east in good condition. Found R. Fraser's 3/4" x 1 1/2" iron at the property corner west in good condition.

7-20-2011 County survey crew found 3" x 9" stone at the 1/16th corner east down 1' in good condition.

7-28-2011 County survey crew set 4' telspar pipe with cast iron cap down 0.9' at previously measured location using Traverse Drawing 4-1 after field verification of the 1/16th stone east and R. Fraser's iron at property corner west.