Certificate of Location of Government Corner

ID#:521706 **Description:** 1/4 SEC COR 17 18 52 **Date Set:** 4/19/1977 **County:** Olmsted

Section: 17 **Township:** 105N **Range:** 12W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The monument is at the surface
The corner falls 22' west of fence south and 7' south of centerline of E-W twp road
County Survey Disk in E side fence post N 30.80'
County Survey Disk in N side fence post ESE 42.20'
This corner is located by GPS measurement.

Corner History:

10-1853 Gov't Notes William A. Jones, Deputy Surveyor North between sections 17 and 18. 40.00 chs. Set quarter section post-deposited stone. Dug trench and pits. Made mound and planted cherry seeds N.E. and S.W.

5-1878 Thomas Hunter, County Surveyor, (P. 345 No. 338) states that corner was gone, cut a settler, Mr. Burnap, avers he set the corner fence post beside the original stake so used the West side of the corner post as the corner.

6-1902 Robert Fraser, County Surveyor, (P. 710 No. 624) states that the corner was washed out and all evidence gone. Set a stake midway and on line.

4-1905 Robert Fraser (P. 82B) found a stake with an iron by its side which came on the South side of the road and 10 lks. or more West of the fence-corner set in a previous survey midway and on line.

4-15-1977 County Surveyor dug 16' N-S by 11' E-W centered midway and on line between the Section Corner 7-8-17-18 and the corner post at Sec. Cor. 17-18-19-20. Found nothing.

4-19-1977 County Surveyor set a Cast Iron Cap on a square pipe as the corner midway and on line from Sec. Cor. 7-8-17-18 to a Cast Iron Cap set by the corner post as Sec. Cor. 17-18-19-20. The corner came 7' south of the centerline of the old road and 22' west of the fence South.

2-23-2011 County survey crew found cast iron cap on square pipe in good condition.