Certificate of Location of Government Corner

ID#:521806 **Description:** W 1/4 SEC COR 18 52 **Date Set:** 4/28/1977 **County:** Olmsted

Section: 18 **Township:** 105N **Range:** 12W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls in woods
Spike in W side 7" blazed Elm NNW 22.92' (grown over)
Spike in S side blazed 15" Red Oak (most southerly of triplet) WSW 41.89' (grown over)
Spike in N side 9" blazed Maple SE 6.82' (grown over)
Post w/sign 1' east
This corner is located by GPS reference stations "521806 A & B"

Corner History:

10-1853 Gov't Notes John Ball, Deputy Surveyor North between sections 13 and 18. 35.50 chs. Brook 4 lks. wide runs NE 40.00 chs. Set post. Black Oak 18 in. S44°E 26 lks. Black Oak 12 in. S70°W 8 lks.

2-1873 Thomas Hunter (P. 190 No. 201), County Surveyor, reset the corner from the existing bearing trees and the stump of a bearing tree. Set a stake at the Center 13.

2-1874 T. Hunter (P. 239 No. 241) found the stake set P. 190 and found the stake at the Center 13.

1-1876 T. Hunter (addition to P. 239 No. 241 and Field Book 4 P. 98) found the stake.

5-1878 T. Hunter (P. 345 No. 33 8) found the Bearing trees. Reset a new marked stake.

1-1894 William Fraser (P. 541 No. 502) found the stake at the Center 13 and set a stone there.

5-6-1965 County Surveyor dug on the NW side of the corner post and found a hole leading into the subsoil. Dug down and found pieces of charred wood 2' deep.

4-28-1977 County Surveyor set a Cast Iron Cap on a square pipe as the corner 1.4' North of the hole found 1975 and on the line from the W 1/4 corner 13 (found) over the Center 13 (found). The corner is 3' North of the corner post and 1/2' West of the N-S fence.

1-16-2008 County Surveyor found cast iron cap on telspar pipe up 0.7' in good condition.

10-28-2009 County Surveyor found cast iron cap on telspar pipe up 0.7' in good condition.