Certificate of Location of Government Corner

ID#:521904 **Description:** 1/4 SEC COR 19 30 52 **Date Set:** 7/10/2009 **County:** Olmsted

Section: 19 **Township:** 105N **Range:** 12W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 9' east of centerline of twp road south and 6' east of fence north
60d in root on W side 30" Burr Oak N 54.0'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes East on true line between sections 19 and 30. 40.00 chs. Set quarter section post. Deposited stone 3"x2"x2". Dug trench and pits and made mound and planted acorns NE and SW.

6-1894 William Fraser (P. 546 No. 506), County Surveyor, states corner gone. Reset corner with stake and stone 3"x6"x16" on line and at proportionate gov't measure.

5-15-1973 County Surveyor found recorded stone 6' deep. Set a CIM over a 3/4"x16" iron with original stone on set side of the monument.

7-10-2009 County Surveyor found CIM down 1.1' in good condition. Took ties and removed. Found 5/8" rerod down 2.8' in good condition and removed. Set a 6' telspar pipe w/CIC down 0.5' at CIM location.