Certificate of Location of Government Corner

ID#:521906 **Description:** W 1/4 SEC COR 19 52 **Date Set:** 7/16/2009 **County:** Olmsted

Section: 19 **Township:** 105N **Range:** 12W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls in centerline of CR 139 south and in centerline of CR 139 west
Bottle cap in NW side CP NE 44.01'
Bottle cap in NE side PP #13237 SE 44.73'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes John Ball, Deputy Surveyor North between sections 19 and 24. 40.00 Set quarter section post. Burr Oak 10 in. S55ºE 100 lks. Burr Oak 8 in. N12ºW 197 lks.

9-1885 Thomas Hunter (P. 403 No. 392), County Surveyor, states corner gone. Set unmarked stake 50 lks. west of corner of fence east and in center of road and in line with fence east.

6-1894 William Fraser (P. 546 No. 506), County Surveyor, relocated corner as close as possible to Hunter's notes. Set limestone as corner.

5-14-1973 County Surveyor found 4"x6"x24" limestone and set a CIM over stone with an iron rod beside stone.

9-13-2002 V. Fangman set 1/2" pipe w/cap RLS #14888 over CIM.

7-10-2009 County Surveyor found 1/2" pipe down 0.4' in good condition.

7-16-2009 County Surveyor removed 1/2" pipe and found CIM down 1.6' in good condition. Removed CIM and found 5" x 11" x 26" stone down 2.7' in good conditiion. Removed stone and set 6' telspar pipe w/Cast Iron Cap down 0.5' at CIM position.