Certificate of Location of Government Corner

ID#:522006 **Description:** 1/4 SEC COR 19 20 52 **Date Set:** 7/10/2009 **County:** Olmsted

Section: 20 **Township:** 105N **Range:** 12W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls in centerline of E-W twp road, 1' east of centerline of twp road south and 3' east of fence north
Concrete nail in E side 6" White Cedar CP SW 58.0'
Bottle Cap in NE side PP #13271 SE 46.31'
This corner is located by GPS measurement

Corner History:

10-6-1853 Gov't Notes North between sections Var 10°55'E 19 & 20 variation 10°55'E at 40.00 set quarter post. Aspen 7" N71°E 31 lks. White Oak 5" N22°W 18 lks.

6-1857 T. Hunter P. 32 No. 50&51 Used corner 1/16 West 19.66 M&L Meas. to Center 20 East 39.89 M&L.

6-1894 W. Fraser P. 546 No. 506 Found stone planted 20 yrs. before from orig. stake 1/16 so. set boulder stone & stake 19.891/2 M&L. Drove stake east M&L to center 20. 1/16 W. found stake driven by T. Fraser M&L.

4-1905 R. Fraser P. 80 B Found stone P. 546 Found stone on line E 25.08 chs. Set stake E 11.28 chs. Found long stone at center 20.

5-17-1973 County Surveyor ran & meas. line from 19-20-29-30 No. searched for bldr. - Found nothing. Continued line to 2626± and found 12"± square mark in clay where stone had been. Set rod in center of mark. Ran elec. line east & found 6x6x? limestone found by R. Fraser (4-1905).

4-4-1988 Roger Brand and Associates set 5/8" rebar in place of 1/2" bar.

7-10-2009 County Surveyor found 5/8" rerod down 0.7' in good conditioin. Took ties and removed. Set 4' telspar pipe w/CIC down 0.4' at rerod location.