# Certificate of Location of Government Corner

**ID#:**522104 **Description:** 1/4 SEC COR 21 28 52 **Date Set:** 7/7/2009 **County:** Olmsted

**Section:** 21 **Township:** 105N **Range:** 12W **Monument Description:** Cast Iron Cap on telspar pipe

**Reference Ties:**

The corner falls 20' east of centerline of CR 139
County Survey Disk in E side PP #43693 NNE 39.43'
County Survey Disk in fence post SE 27.57'
County Survey Disk in W side PP #43693 NNE 39.39'
This corner is located by GPS measurement

**Corner History:**

10-6-1853 Gov't Note West on true line between sections 21+28. VAR 9°55'E 40.07 Set qr. section post ELM 8N23W 24' MAPLE 8S61E 30' 80.14 to section corner

7-1856 T. Hunter Pg. 12 No. 19 shows 1/4 post. 1/16 W 20.18 chs. M&L - Bearing trees (S 32 1/4°E 33 lks.) & (S63 1/4°W 37 lks.) 1/64 e. 9.89 chs. Then 9.89 chs. To 1/16 corner then 19.78 chs. To sec. corner Bearing Tree's to 1/64 East (N 55 3/4°W 4 lks.) & (S 60°E 25 lks.) Bearing Tree's to 1/16 East (N 15 1/4°W 21 lks.) & (S 87 3/4°W 30 lks.)

4-1900 R. Fraser P. 670 No. 596 found long limestone in fence line so. With top broken off (claimed by settlers to be where original gov't stake stood. 1/16 S. Found stone set by Hunter.

10-12-1976 County Surveyor dug from 9'N to 12'S & 3'E & W of traverse nail (found nothing).

12-8-1976 County Surveyor set 3/4" x 15" pipe as final corner by doubling the line & distance from NW 28' over the 1/16th CP E of the NW corner Sec. 28. Corner comes 20'E of center of road.

1-24-1983 Land Consultants found and used pipe as corner for survey in SW 1/4 section 21-105-12.

4-29-1995 GGG found and used pipe as corner for survey in NW 1/4 section 28-105-12.

7-7-2009 County Surveyor found 3/4" pipe down 0.7' in good condition. Took ties and set 5' telspar pipe w/Cast Iron Cap down 0.2' over pipe.