Certificate of Location of Government Corner

ID#: 522409 **Description:** SEC CEN 24 52 **Date Set:** **County:** Olmsted

Section: 24 **Township:** 105N **Range:** 12W **Monument Description:** Note: Information regarding this center of section is provided for reference purposes only. A professional land surveyor should make the decision whether to use any existing survey monument or the computed intersection of quarter lines.

5/8" pipe with cap RLS #8952

Reference Ties:

The corner falls 1/2' north of fence west
The monument is down 0.2'
This corner is located by GPS measurement

Corner History:

4-16-1878 Thomas Hunter, County Surveyor, (Book A, Page 336, Survey No. 330) set stake at intersecting quarter lines. 1/16th West stake midway and on line at 19.83-1/2 chains (1309.11') to West 1/4.

12-17-1987 County Survey Crew dug and found stake hole down 0.5' in clay between two corner posts. Set 40d spike at surface over 20d spike in stake hole. The corner falls just NE of corner post to fences east and south and 1' east of corner post for fence west.

7-26-2006 GGG used computed center at intersecting quarter lines.

4-25-2012 County Survey Crew could not find 40d spike, but did find 5/8" pipe with cap RLS #8952 down 0.2' in good condition and measured its position using GPS.

3-28-2013 G-Cubed used computed center at intersecting quarter lines.

11-30-2015 Joel Thoreson, County Surveyor, recommends using the computed intersection of quarter lines for the center of section. Based on the county's section breakdown, the 5/8" pipe w/cap, as located by GPS in 2012, falls 1.31' north and 0.78' east of the computed center.