Certificate of Location of Government Corner

ID#:522504 **Description:** 1/4 SEC COR 25 36 52 **Date Set:** 2/23/2005 **County:** Olmsted

Section: 25 **Township:** 105N **Range:** 12W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 10' east of N-S fence and in line with remnants of fence east
County Survey Disk in E side 36" Aspen S 25.28'
County Survey Disk in N side 18" Aspen up 2.5' E 27.22'
Post w/sign 2' east
This corner is located by GPS reference stations "Marmaduke A & B"

Corner History:

1853 Gov't Notes West on true line between sections 25 and 36. 39.94 chs. Set quarter section post. White Oak 9 in. S13ºW 38 lks. White Oak 9 in. N9ºE 13 lks.

4-1878 Thomas Hunter (P. 336 No. 330), County Surveyor, found NE bearing tree standing but others gone. Found stake remains and drove new stake in its place. Set 1/16 stake north.

5-1886 T. Hunter (P. 405 No. 394) found marked stake and tested with bearing tree stump.

4-1893 William Fraser (P. 505 No. 475), County Surveyor, found 1/16 stake north on south bank of river.

6-20-1973 County Surveyor set a CIM over an iron rod on east side of corner post proven by electronic measurement around section 25 and old post stub found where monument is set.

7-13-1977 Mn/DOT found CIM flush with gound.

2-14-2005 County Surveyor found CIM leaning ESE up 0.1'.

2-23-2005 County Surveyor found CIM leaning, took ties and removed, found iron rod in good condition down 1.9' took ties. Set 7' telspar w/CIC over iron rod up 0.3'. CSD in east side of 36" Aspen south 25.28' and CSD in north side of 18" Aspen up 2.5' east 27.22'. Monument falls 10' east of N-S fence along edge of field and inline with remnants of fence running east. Set sign and post 2.0' east.