Certificate of Location of Government Corner

ID#:522604 **Description:** 1/4 SEC COR 26 35 52 **Date Set:** 10/12/1978 **County:** Olmsted

Section: 26 **Township:** 105N **Range:** 12W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The monument is at the surface.
The corner falls 6' east of fence north, in line with fence south and 23' north of fence east
County Survey Disk in SE side 12" blazed Burr Oak NE 140.70'
County Survey Disk in N side blazed 26" Burr Oak ENE 61.94'
County Survey Disk in N side 14" Burr Oak ESE 79.23'
Post with sign north 2'
This corner is located by GPS measurement.

Corner History:

10-1853 Gov't. Notes William A. Jones, Deputy Surveyor West on true line between sections 26 and 35. 40.00 chs. Set quarter section post. Red Oak 7 in. S7ºE 201 lks. Aspen 8 in. North 38 lks. 80.00 chs. To section corner.

5-1877 Thomas Hunter (Book A. P. 312 No. 306), County Surveyor, states: "at F (1/4 Cor. 26-35) 1/4 post missing as usual, but found both witness trees, the distance however as given in the field notes for the Red Oak would carry it North of the Aspen, the other witness tree. We did not therefore set a new 1/4 post, but as the Aspen witness tree was on the N & S line which ever side of the tree the corner stood, we ran North from said tree."

2-1902 William Fraser (Book B P. 30), County Surveyor, states: "at B (1/4 Cor. 26-35) This corner was gone but Frank Bernard affirmed that he nailed the fence to the Aspen B.T. and part of the tree laid by the side of fence and we found the stump which was just on east side of fence and we used the center of said old stump which was 6" east of the wire on the fence for purposes of this survey." Fraser found an iron at the S 1/4 Cor. 35 and set an iron at the Center 35 at intersecting 1/4 lines.

10-12-1978 County Surveyor set a Cast Iron Cap on a square pipe as the corner at the intersection of the line from the S. 1/4 Cor. 35 (found) over the Center 35 (found) and the line from the N.W. Cor. 35 (found) to the NE Cor. 35 (as set this survey). We decided to locate this corner on line between the section corner since neither Hunter in 1877 or Fraser in 1902 were able to determine the N-S location of the corner and neither described an E-W fence at the corner. The corner is in line with the fence South, is 6' East of the fence North, and is 23' North of the main line of the fence East.

4-8-2011 Olmsted County survey crew found CIC in good condition.