Certificate of Location of Government Corner

ID#:522606 **Description:** 1/4 SEC COR 26 27 52 **Date Set:** 4/12/1979 **County:** Olmsted

Section: 26 **Township:** 105N **Range:** 12W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The monument is down 0.1'
The corner falls in a pasture 45' north of centerline of E-W ditch
County Survey Disk in N side 20" Hickory NW 145.1'
County Survey Disk in N side 18" blazed Basswood ESE 75.45'
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes William A. Jones, Deputy Survey North between sections 26 and 27. 40.00 chs. Set quarter section post. Burr Oak 12" N26ºE 9 lks. Burr Oak 10" N84ºW 8 lks.

5-24-1877 Thomas Hunter (Book A P. 312 No. 306), County Surveyor, states that the corner was gone. He set a stake as the corner from the bearing trees. Set stakes at the 1/16th East, the Center 26, and the 1/16th East of the Center 26.

10-1978 County Surveyor projected the line from the East 1/4 Cor. 26 over a stone found at the 1/16th West and dug from a point at Hunter's full 1877 measure from the East 1/4 Cor. North and East but did not find anything.

4-12-1979 County Surveyor returned to the corner to check two tree stumps as possible stumps of the original bearing trees. The center of the northerly stump was rotted out and when we looked inside the old blaze was plain and we could see where the growth had filled in the scar (we removed this portion of the stump to the office). We set a point at the Gov't measure and bearing from this stump and the bearing and distance from this point to the westerly stump agreed with the Gov't notes. The point came at the N.E. corner of our previous digging so we dug again but did not find anything. We accepted the stumps as the stumps of the original Gov't bearing trees and set a Cast Iron Cap on a square pipe as the corner from the stumps.

4-15-2011 County survey crew found cast iron cap on square pipe in good condition.