Certificate of Location of Government Corner

ID#:522805 **Description:** SEC COR 28 29 32 33 52 **Date Set:** 6/11/1981 **County:** Olmsted

Section: 28 **Township:** 105N **Range:** 12W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls in centerline of E-W twp road, in line with fence north and 10' east of centerline of field entrance south
County Survey Disk in E side fence post N 34.10'
County Survey Disk in SE side PP #13445 NE 50.38'
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes William A. Jones, Deputy Surveyor North between Sections 32 and 33. 80.00 chs. Set post - Corner to Sections 28, 29, 32 & 33. Red Oak 9 in. S69ºE 46 lks. Red Oak 10 in. N60ºE 41 lks. Red Oak 10 in. N47ºW 42 lks. Red Oak 7 in. S601/2ºW 46 lks.

11-1856 W.H. Mills, Surveyor, (Old Road Book, Road No. 50) surveyed a road between Section 29 and 32 but gives no description of the corner here.

9-17&18-1879 Thomas Hunter, County Surveyor, (Book A. Page 363, No. 354) "found the remains of an old stake from stumps of B.T. in the ground very rotten." He set a stone 15"x5"x21/2" in its place with broken stone under it and around the bottom. He used this corner to set the 1/16W, a stake, midway and on line to 1/4 Cor. 29-32, a stake set midway between N.E. 32 and N.W. 32.

4-1885 Hunter (Book A, Page 395, No. 385) found stone set in Survey 354. He used the corner to set the 1/16 East midway (19.931/2 chs.) and on line to 1/4 Cor. 28-33.

4-1901 William Fraser, County Surveyor, (Book B, Page 2) "found stone set as corner." He used this corner to set the 1/16W, a stake and stone, on line and midway (19.96 chs.) to 1/4 Cor. 29-32, an iron stake in the center of the road and midway (39.94 chs.) between the section corners.

6-10-1981 County Surveyor dug and found a 21/2"x5"x15" stone and old stake packed in smaller stones 31/2' deep. Placed a 3/4"x1' iron in the stake hole and placed the stone over the iron. Placed a 3/4" iron on the West side of the stone and a 5/8" iron on the East side of the stone and packed all in pieces of stone as found.

6-11-1981 County Surveyor placed a CIM over a R.R. spike at the road surface and over the corner found 6-10-1981.

11-15-1994 County Surveyor found CIM in good condition in E-W twp road.

11-5-2008 County Surveyor found CIM down 0.7' in good condition.