Certificate of Location of Government Corner

ID#:522906 **Description:** 1/4 SEC COR 29 30 52 **Date Set:** 7/20/2009 **County:** Olmsted

Section: 105 **Township:** 105N **Range:** 12W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls in line with E-W fence and 4 1/2' east of N-S fence
60d spike in 12" Cherry SE 16.37'
60d spike in S side 28" White Oak ENE 25.75'
Rivet in S end 18" CMP NE 7.11'
Post w/sign 1' east
This corner is located by GPS reference stations "Reichel A & B"

Corner History:

10-6-1853 Gov't Notes North between sections 29 & 30. VAR 10°30'E 40.00 set qr. section post Aspen 5"S70°W 24 lks. W. Oak 5"N851/2°E 48 lks. 52.50 Brook 5 lks. wide runs east d80 65.00 Enter grubby prairie bears E & W A100

4-1901 W. Fraser P.2B Corner gone and no evidence to locate it. Set stake M&L 39.76 chs. 1/16 East drove oak and iron stakes M&L 19.99 chs. 1/16 South drove iron stake M&L 19.88 chs.

8-31-2000 GGG set 1/2" pipe w/cap RLS #21940 at lost position between section corners.

6-29-2009 County Surveyor found 1/2" pipe w/cap RLS #21940 up 0.1' in good condition.

7-20-2009 County Surveyor referenced and removed GGG 1/2" pipe and then dug with backhoe in line of fences E-W-N-S looking for W. Fraser's M & L stake. Found 1" x 40" shaft down 1/2', 5' NE of GGG 1/2" pipe. Replaced 1" x 40" shaft with 6' telspar pipe w/Cast Iron Cap down 0.4'