Certificate of Location of Government Corner

ID#:523306 **Description:** 1/4 SEC COR 32 33 52 **Date Set:** 11/15/1994 **County:** Olmsted

Section: 33 **Township:** 105N **Range:** 12W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls between two corner posts and under E-W fence
Sign on CP 1/2' SW
This corner is located by GPS measurement

Corner History:

10-6-1853 Gov't Notes North between section 32+33 10.00 in dry hollow 16.00 Enter thickets 33.40 Brook 6 lks. Wide runs east 40.00 set qr. Section post Burr Oak 6" S101/2°E 472' W. Oak 6" N15°W 320'

9-1881 T. Hunter (Book 5, P. 125) 1/16 W. M&L 20.071/2 chs; 1/16 S. M&L 19.931/2 chs.

4-1885 T. Hunter P. 395 No. 385 Found stake, tested only remaining Bearing tree, left as found. 1/16 east corner comes in creek M&L 19.83 chs.

2-1904 C. Armstrong P. 72 B. Corner marked on plat as iron stake.

8-24-1979 County Surveyor dug small hole on east side of corner post to fence W-E-N. Dug further & found the stubs of two old corner posts. Did not dig any further.

11-15-1994 County Surveyor found a 30" oak tree south 10 1/2 degrees east of corner cluster ± 311' this being bearing and distance of gov't witness tree used by T. Hunter to verify stake he found. We set a cast iron cap on telspar pipe at bearing and 311.52' from 30" witness tree.

11-10-2008 County Surveyor found cast iron cap on telspar pipe up 0.3' in good condition.