Certificate of Location of Government Corner

ID#:523506 **Description:** 1/4 SEC COR 34 35 52 **Date Set:** 6/15/1999 **County:** Olmsted

Section: 35 **Township:** 105N **Range:** 12W **Monument Description:** Cast Iron Monument

Reference Ties:

The monument is down 0.3'
The corner falls 3' of west of centerline of driveway and 12' south of short fence west
County Survey Disk in SE side 29" Hackberry NE 40.62'
This corner is located by GPS measurement.

Corner History:

9-1853 Gov't Notes William A. Jones, Deputy Surveyor North between sections 34 and 35. 40.00 chs. Set quarter post. Elm 12 in. S8ºW 58 lks. Hackberry 8 in. S73ºE 50 lks.

12-1877 Thomas Hunter (unrecorded survey in Old Field Book No. 5 P. 33), County Surveyor, used this corner to survey the SE 1/4, Sec. 34. He records the true bearing trees at 1/4 corner 34-35: N881/2ºE (?) Hackberry 15 in. S75ºW 33 lks. Elm 18 in.

2-1902 William Fraser (Book B P. 30), County Surveyor, found stone set as corner with stake by side and Elm bearing tree S76ºW 33 lks. with marks plain. Set a sleigh shoe at the 1/16th North, an iron at the 1/16th East, an iron at the Center 35, and a sleigh shoe at the 1/16th East of the Center 35. Also set an iron at the NW corner 35.

2-1904 C. Armstrong (Book B P. 72) found stone by the fence corner and the Elm bearing tree.

8-10-1978 County Surveyor found Fraser's irons at the 1/16th North, the NW corner 35, the Center 35, and the 1/16th East of the Center 35. Set a Cast Iron Cap on a square pipe 2' long as the corner at the intersection of the line from the NW corner 35 over the 1/16th South and the line from the 1/16th East of the Center 35 over the Center 35. The corner came at the North end of an old stone bridge so we could not dig for the corner.

6-15-1999 County Surveyor set 16" CIM over 5/8"x18" rerod from ref tie line from south.

7-15-2009 County Surveyor found CIM down 0.3' in good condition.

4-7-2011 County survey crew found CIM in good condition.