Certificate of Location of Government Corner

ID#:523606 **Description:** 1/4 SEC COR 35 36 52 **Date Set:** 8/10/1978 **County:** Olmsted

Section: 36 **Township:** 105N **Range:** 12W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 21' south of centerline of TH 30 and 27' east of centerline of driveway north at mailbox #13011
County Survey Disk in CP NNW 99.95'
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes Williams A. Jones, Deputy Surveyor North between sections 35 and 36. 30.05 chs. Enter pond E & N. 40.00 chs. In pond. 40.50 chs. Set witness corner to quarter section corner. Burr Oak 8 in. S68ºE 73 lks. Burr Oak 6 in. N65ºW 78 lks.

5-1886 Thomas Hunter, County Surveyor, (Book A P. 405, No. 394) states: "1/4 post and witness corner missing. Found stump of SE Witness tree with marks all plain from which we reset a new witness corner 50 lks. North of true corner, the true corner coming in the edge of a pond hole".

2-1902 William Fraser (Book B P. 30), County Surveyor, drove an iron stake as the corner 73 lks. From the SE bearing tree stump (marks still plain) and 50 lks. From the witness stake north of the corner. Drove an iron at the Center 35 and an iron at the 1/16th East of the Center 35.

8-10-1978 County Surveyor set a CIM over a 1/2"x2' rod at double the line and measure from the Center (found) over the 1/16th East (found). This corner comes in very deep fill in T.H. 30 so could not dig for the corner. The witness stake 50 lks. North would fall under the bituminous surface of TH 30. We have reset this corner according to Fraser's 1902 survey. This location could differ from Hunter's corner since Fraser mistakenly used the bearing tree distance as the distance to the 1/4 corner instead of to the witness corner. However, computation will show (see County Surveyor) that the difference between the corners would be coincidently slight and since at this time we have no other means of recreating Hunter's exact location, we will accept the corner as set which will agree with the other monuments found in Sec. 35.

6-10-1999 County Surveyor found CIM in good condition.

8-30-2006 County Surveyor found CIM down 0.4' in good condition.