Certificate of Location of Government Corner

ID#:530209 **Description:** SEC CEN 2 53 **Date Set:** 9/14/2007 **County:** Olmsted

Section: 02 **Township:** 105N **Range:** 13W **Monument Description:** Note: Information regarding this center of section is provided for reference purposes only. A professional land surveyor should make the decision whether to use any existing survey monument or the computed intersection of quarter lines.
5/8" rebar with cap RLS #42198

Reference Ties:

The monument is down 0.4'
The monument falls 1' east of centerline of N-S road and 2' south of road east
This corner is located by GPS measurement

Corner History:

8-1940 J. Kerr Bk.20 Pg.62-65; Set 3/4" bolt 3.5' long at intersecting lines. Took measurements east,west,and north. RPs- 24" maple SSW 33.0, 18" maple SW 63.7.

7-22-1968 J. Kerr found rod, set CIM over with broken pottery. Measured to 1/4 east 2640.2, (John 1940 2640.6). Set rod on line east near 80 rod joint 26.6' north of telephone pole north of centerline road, 35± west of center field drive south. Measured to section corner north 2592.6 (John 1940 2591.2), measured west 1940 2634.9.

8-11-1982 Olmsted County Surveyor found Kerr's CIM 4' west centerline N-S road and 4' west of both centerline road east and line of fence west. Removed CIM, but left bridge bolt beneath in place.

9-14-2007 WHKS & Co. set 5/8" rebar with cap RLS #42198 at intersecting quarter lines as center of section 2.

8-3-2011 County survey crew found 5/8" rod with cap #42198 in good condition