Certificate of Location of Government Corner

ID#:530304 **Description:** 1/4 SEC COR 3 10 53 **Date Set:** 8/3/2009 **County:** Olmsted

Section: 03 **Township:** 105N **Range:** 13W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls under N-S PP line and 4' south of centerline of ravine
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes M.G. Karrick East Ranilom 3 & 10. 40.00 set temp 1/4 section post West on true line between section 3 and 10 9°57'. 40.00 set 1/4 section post. Bur Oak 8 N 35 E 77. Bur Oak 15 S 52 E 153.

9-1884 T. Hunter (P 392 No 383) W. Pierson found stone and stake in place, bearing tree gone could not test corner, accepted and left as is. No measure.

1-1894 W.Fraser Pg.542 No.503; Found stone set stakes every 10.01 west to section stone found.

6-1917 J. Kerr (P 266 B) (Field Book 10 P. 13-15 also Kerr Bk. 20 p. 62). W. Haney etal found 4 x 8 x 18 stone in edge dry run. Meas West 2640.7 to sec. corner stone. Bearing trees 10" J Oak N 44° W 5.4'. 8" J Oak N 70° 30 E 20.1.

1965 J. Kerr for setting corner run line N 1/4 3 South. Found at S 1/4 3 a deep wash some 6' deep and 8' wide at location recorded stone. REA cut all trees stumps resembling NW BT 1917 still in place. Gully took NE tree. Assumed spot of corner set 1/2" rod on true line (ran on 5' offset east) on rise some 300' + North within 1.5' Northwesterly of pole. No measure from N section corner stone West completely gone also.

2-1976 County Surveyor set 1/2" x 4' pipe up 3' in wash at double the line and measure of computed location. Sec. corner 3-4-9-10 over thresher cylinder at 1/16 East. Pipe in line of fence South and 2' S fence West. Note: Pipe location requires slight correction before final corner is set.

Since 3-4-9-10 finalized, pipe in correct location at 1/4 3-10.

11-14-2003 County Surveyor visited area of corner. Found nothing.

8-3-2009 County Surveyor set 3 1/2' telspar pipe w/CIC up 0.5' from RTK stake-out.