Certificate of Location of Government Corner

ID#: 530505 **Description:** SEC COR 5 6 7 8 53 **Date Set:** 3/13/1973 **County:** Olmsted

Section: 05 **Township:** 105N **Range:** 13W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls in a field, 6' south of fence east, 13' NW of fence NE and 30-1/2' west of corner post to fences NE & east
The monument is down 1.1'
Sign in corner post 30-1/2' east
This corner is located by GPS measurement

Corner History:

5-24-1854 Michael G. Karrick, Deputy Surveyor, measured 80.00 chains north between Sections 7 and 8. Set post in mound with trench, pits and charred stake. Planted Osage Orange seeds at each angle.

7-12-1856 Thomas Hunter, (Book A, Page 13, Survey No. 21), used corner. 1/16th East set midway and online at 20.11 chains (1327.26').

9-24-1891 Thomas Fraser, County Surveyor, (Book A, Page 458, Survey No. 442), states corner had been lost in the grading of the railroad. Set 5"x6"x20" stone by railroad notes. 1/16th East found stone at 20.10-3/4 chains (1327.10'). 1/16th West found stone at 20.08-1/2 chains (1325.61').

6-1892 William Fraser, County Surveyor, (Book A, Pages 502-503, Survey No. 472), found stone. 1/16th West set stone midway and online.

10-14-1905 Charles Armstrong, County Surveyor, (Book B, Pages 98-99), 1/16th West stone at 20.04 chains (1322.64').

5-10-1958 John Kerr, County Surveyor, (Kerr Field Book No. 73, Pages 5-6), found boulder with 3/4" pipe on south side. RPs - Whistle Stop post WSW 43.55', Inside rail ESE 10.7'. 1/16th North set 1/2" rod midway and online at 1315.83'.

10-17-1962 County Highway Department found limestone. RPs - Telephone pole NW 34.0', Concrete marker post SW 37.0'.

7-28-1964 John Kerr, County Surveyor, found pipe in stones. Set Cast Iron Monument over 1"x12" pipe. RPs - Notch in SE corner Whistle Stop post WSW 43.55', Inside north rail ESE 10.7', 20d spike south side telephone pole NW 39.1', 120d spike north side Willow W 92.0'.

8-4-1969 John Kerr, County Surveyor, (Kerr Field Book No. 98, Page 76), found Cast Iron Monument. The corner falls in railroad ditch.

3-13-1973 Roger Brand, County Surveyor, dug and found recorded size boulder. Set Cast Iron Monument at surface over boulder with pieces of railroad irons by stone. Removed Cast Iron Monument set by John Kerr. The correct corner is 5'± south and 7' west of John Kerr's location. RPs - SE corner Whistle Stop post WSW 37.5', Inside north rail ESE 10.72', 20d spike SW side telephone pole NW 33.55', Center old post NNE 44.45'.

Correction of a Corner: The correct corner is 5.0' south and 7.0' west of Cast Iron Monument set by John Kerr (removed).

4-20-1976 County Surveyor, 1/16th North found 1/2" rod set by John Kerr and removed. Set 3/4" rod midway and online, after correcting SW Section Corner 5, at 1317.64'. The corner falls 2.8' south and 3.8' west of 1/2" rod position.

4-11-1978 County Survey Crew, 1/16th North found 3/4" rod in good condition and referenced prior to road resurfaced. The corner falls 3' south of centerline of CSAH 16. RPs - Chisel mark in top south end RCP WSW 178.40', County Survey Disc in SW side power pole #43786 NW 92.00'.

4-16-1981 County Survey Crew found Cast Iron Monument in good condition. Railroad bed being leveled to the east of this corner puts corner monument in danger of being destroyed. We talked to dozer operator and he said he would work around the monument location if we marked it. Existing ties will probably be destroyed. RP - County Survey Disc in RR tie corner fence post E 113.1'.

3-1-2006 County Survey Crew found Cast Iron Monument down 1.1' in good condition and measured its position using GPS. The corner falls in a field, 6' south of fence east, 13' NW of fence NE and 30-1/2' west of corner post to fences NE and east. Set sign in corner post 30-1/2' east.