Certificate of Location of Government Corner

ID#:530506 **Description:** 1/4 SEC COR 5 6 53 **Date Set:** 8/4/1969 **County:** Olmsted

Section: 05 **Township:** 105N **Range:** 13W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 1' south of E-W fence
Post w/sign 2' south
Steel fence post 1/2' east
This corner is located by GPS reference stations "Janvrim A & B"

Corner History:

1854 Gov't Notes M.G. Karrick N. Random 5 and 6 40.00 set a temp 1/4 section post S 9' E on true line between section 5 and 6 39.80 set 1/4 section post in mound with trench, pitts, charred stake and planted Osage Orange seed NE and SW

7-1856 T. Hunter P.13 No.21 used corner and set 1/16 East 19.98 to center 5

6-1892 W. Fraser (P.502 No. 472) found stone placed from original stake by J. O'Neal 1/16 North set stone M & L (possibly gov't prorated which would be 19.84 S 1/2 & 19.64 1/4 N 1/2) no meas. 1/16 West set stone M & L no meas. (see T.F. Field Bk 8 p. 28).

7-31-1969 J. Kerr attempted to find corner post by walking line no N-S fences great masses of brush and weeds, investigated one corner for field fence starting South found 200' + too far West.

8-4-1969 J. Kerr found limestone at fence corner as recorded and placed cast iron monument on top of stone. Note: 1/16 iron set in black top on road West of Simpson but still in place-spud in power pole NE 109.4. Spud in tele pole SE 70.8.

8-4-1969 County Surveyor ran line from 5-6-7-8 over 1/16 rod in black top set in 1958 using searched for corner post as corner at that time. Corner proved in meas of brush and weeds. Found stone about on foot SW of corner post limestone 6 x 8 x at leat 16" in clean black soil about 14" down set full size CIM in top with bent 1/2" rods on N and S side of stone- cans and junk on E side of stone. Steel post up 1 1/2' .35' East of CIM mounded dirt around entire area to come to top of CIM 4" boxelder trimmed to single trunk NW 2.3' in fence line old corner post rotted off but wires tied on from E and W.

7-15-1977 County Surveyor, 1/16 N found M & L point came at the corner post. Dug around post and found many small stone pieces but found nothing further.

3-6-2006 County Surveyor found CIM up 0.2' in good condition.