Certificate of Location of Government Corner

ID#:530604 **Description:** 1/4 SEC COR 6 7 53 **Date Set:** 5/2/2007 **County:** Olmsted

Section: 06 **Township:** 105N **Range:** 13W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

Post w/sign 2' south
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes M.G. Karrick, Deputy Surveyor East between sections 6 and 7. 39.60 chs. Set quarter section post in mound with trench, pits, charred stake, and osage oranage seeds N.E. and S.W.

6-1892 William Fraser (P.502 No.472), County Surveyor, states corner gone. Set a stone 3"x10"x25" at the intersection of the south line of Section 6 and the north-south 1/4 line of Section 7.

5-1917 Chas. Armstrong (book K page 19) plat shows stone at 1/4 corner. 16 East shown meas South 39.86 1/2 2631.09 to center 7.

3-11-1960 M.H.D. N. 1/4 7 found 25" x 3" x 10" stone pointed end up with steel pin flush to stone on South side, no fences in area. Land is being worked all around it. Told farmer about it they want to and will save it. North line sec. 7. I lined up with N.E. Cor. Sec. 7 that J. Kerr set & N 1/16 Cor. And missed the N. 1/4 Cor. By 5' South, I think Kerr pin should move 5' South or 1/16 Cor. Should by moved North.

1970 M.H.D. found stone.

3-13-1973 County Surveyor found limestone 2"x10"x20" 10" deep. Set a 3/4"x8" rod with pieces of limestone very deep with a CIM 16" deep over all. There are no fences in the area now - only a bulkhead.

5-4-1992 Roger Brand & Associates found and used monument in survey of SW 1/4 of section 6.

6-27-2005 V. Fangman found and used monument in survey of NE 1/4 section 7.

5-2-2007 County Surveyor found CIM down 1.5' in good condition. Took ties & removed. Found 3/4" rod down 3.0' and matching ties of CIM, removed. Set 7.0' telspar pipe w/CIC up 0.3' at CIM location.