Certificate of Location of Government Corner

ID#:530705 **Description:** W SEC COR 7 18 53 **Date Set:** 10/18/2007 **County:** Olmsted

Section: 07 **Township:** 105N **Range:** 14W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls in centerline of CSAH 20 and 5' north of centerline of E-W twp road
County Survey Disk in NW side PP #50645 SW 57.73'
Ref iron E 138.06'
This corner is located by GPS measurement

Corner History:

Gov't Notes 80.00 set post and drove charred stake corner to sections 7-12-13-18. Built mound with trench. Planted S.E. Osage Orange seed & N.E. apple seeds.

6-1886 Hunter (P411 No.400) found stone in center crossroad avered by Mr. Hare to have been planted in center mound where stake was standing by himself and other settlers. Meas South 39.95 to corner stone found.

1943 County Highway Department (Book 137 Page 56) Found a 4" x 5" x 16" limestone monument 1 foot below surface. RP's disc in corner post NW 29.4'. Disc in TP SW 37.5'. Disc in TP NE 32.6'.

1946 J. Kerr (Bk.28 P.36) gives RP #4. Disc in fe. post NW 29.4. Disc in PP SE 37.5. Disc in TP NE 32.6.

1947 County Highway Department found stone buried 5' deep 1 tie.

10-17-1961 J. Kerr found stone while on Tabaccy Road farm survey, set CIM over stone nearly 5' deep to top of stone. Drag tooth driven in 24" oak NE 83.0. Spike or spud power pole SW 45.0. Corner fence post NW 51.0. Lies center crossroads in center County road.

6-13-1989 County Surveyor set 5/8" iron West on line to plastic disk in PP #9675 (this iron falls ± 4' S. of centerline Twp Rd West) set 5/8" iron East on line to plastic disk in PP #9686 (this iron falls in centerline Twp Rd East) angle at W 7-18 angle RT PP #9685 to PP #9675 174° 33'09" to 5/8" re-rod WSW dist. 167.00 to 5/8" re-rod ESE 138.13.

10-21-1991 County Surveyor set 1" square pipe w/cap in new blacktop from transit ties. CR 20 corner is in centerline N-S CR 20 & 5' North of centerline twp rds E & W RP's CSD in PP #50645 SW 57.65'.

1-17-2002 County Surveyor found 1" square pipe w/cap at surface.

6-4-2007 County Surveyor found 1" square pipe w/eroded cap at surface in good condition. Tied out corner for 2007 overlays.

8-29-2007 County Surveyor removed 1" square pipe w/cap for 2007 overlays.

10-12-2007 County Surveyor set pk nail at surface from 2007 overlay tie out.

10-18-2007 County Surveyor set 1" square pipe w/cap at surface over pk nail.