Certificate of Location of Government Corner

ID#:530706 **Description:** W 1/4 SEC COR 7 53 **Date Set:** 10/18/2007 **County:** Olmsted

Section: 07 **Township:** 105N **Range:** 14W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls in centerline of CSAH 20 and in line with fence west
Reference iron E 111.54'
Reference pipe E 246.97'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes: 40.0 set post and drove charred stake for quarter section corner. Built mound, trench, and planted apple seed NE and osage orange seeds SE.

6-1873 T. Hunter unrecorded survey, old book below 152-153, stone set by J.S.Harris.

1892 W. Fraser (BK. A pg. 502) found the stone.

1905 R. Fraser (Bk. B pg. 84) found the corner.

5-1917 Chas. Armstrong (Book K page 19) shows stone with 1/16 stone North. Total 39.94 (2636.04

1942 County Highway Department found the stone.

1964 J. Kerr reset the corner from the County tie and in line with the fence.

9-21-1971 County Surveyor dug with tractor for original stone found first 1892 and by Co. Hwy. Dept. 1942, and never used since. Found limestone with 6" x 8" top 5.2' deep very positive 2.2 West and .9' N of C.I.M. set from County RP's. After finding limestone at W 1/4 7 removed CIM and rod below and set 3' old car bumper jack over stone with 2' rod over jack as temp riser. Too soft to reset CIM RP's W 1/4 7 from reset corner. 62.4 W to East edge of base of concrete corner post. 28.23 NW to tee cross cut in top center 24" conc culv. 33.6 NE to top center East edge of East end conc culv. 102.25 E to square head bolt in center road East figured to be 100' original RP by County Highway Department

Note: This is a correction of a corner, a cast iron monument set by J. Kerr from the county tie. The correct 1/2" x 2' iron rod was then set over the stone. The correct corner is 2.2' W. and .9' N. of where the cast iron monument had been set.

6-13-1989 County Surveyor set 2 1" sq pipes/caps East in old road. The Easterly pipe is in centerline, the Westerly pipe is 1.0' N. of centerline. Angle at W1/4 7, to W'ly RP pipe 111.53. To E'ly RP pipe 246.97. Angle at E'ly RP pipe. Angle RT W 1/4 7 to S'ly roof point at S end main roof St Bridgets Church angle 96° 02 15".

10-22-1991 County Surveyor set 1" square pipe w/cap from transit ties in new blacktop.

3-11-2003 County Surveyor found 1" square pipe w/cap down 0.1' with part of cap broken but center still distinquishable.

6-5-2007 County Surveyor found 1" square pipe w/cap at surface in good condition. Tied out corner for 2007 overlays.

8-29-2007 County Surveyor removed 1" square pipe w/cap for 2007 overlays.

10-12-2007 County Surveyor set pk nail at surface from 2007 overlay tie out.

10-18-2007 County Surveyor set 1" square pipe w/cap at surface over pk nail.