Certificate of Location of Government Corner

ID#:530805 **Description:** SEC COR 7 8 17 18 53 **Date Set:** 6/24/2005 **County:** Olmsted

Section: 08 **Township:** 105N **Range:** 13W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 7' north of centerline of E-W twp road
County Survey Disk in SW side PP SW 49.92'
County Survey Disk in top of fence post N 24.85'
This corner is located by GPS reference stations "Mix A & B"

Corner History:

1854 Gov't Notes M.G. Karrick 80.00 set post in mound with trench, pitts, and charred stake and Osage Orange and each angle from cor. To section 7,8,17 and 18.

5-1856 T. Hunter (P.3 No. 6). Used corner to set 1/16 South 20.07 M & L. 1/16 South set M & L 20.07 2 bearing trees N 86 1/2 W 2.49. S 78 1/4 E 3.02. Hunter (P.4 No.7) S 17. Used corner meas South 40.14.

6-1886 T. Hunter (P.411 No.400) corner completely gone but found 1/16 corner South set (P.3 No.6) which was 20.07 S to 1/4 cor. Did not set section corner at all. (1324.62' also 1/16 South of 1/4 17-18 M & L 20.07 1324.62').

4-30-1973 County Surveyor found nail set in tranverse run 2-26-73 dug with air hammer and shovel, found old road worn to clay 4' deep or better. Found no sign if anything at all. RP's to tranverse nail set center road in line fences N & S. 34.33 S to head of bent 16d nail on W side post. 46.0 SE to short conc nail on NE side PP #9706. 16 S dug to clay, 3' deep SW of corner post undermining area around post found no sign of wood stake. Extreme bottom of corner post down 3' + came about 1.0' N and .3' W of tranise nail (see field notes). Set 16d in road above post. Corner may centr better about .1' N and .1' W of nail in root.

6-20-2005 County Surveyor found nothing.

6-24-2005 County Surveyor set 6' telspar pipe w/cast iron cap down 0.4' from GPS & traverse data.