Certificate of Location of Government Corner

ID#:530904 **Description:** 1/4 SEC COR 9 16 53 **Date Set:** 11/25/2002 **County:** Olmsted

Section: 09 **Township:** 105N **Range:** 13W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

Center of blazed 10" Oak NNW 20.88'
60d spike in W side 20" White Oak SSW 30.95'
Natural mark in S side 7" Red Cedar tree SE 14.8'
NE cor limestone foundation of old house ESE 50.75' (indistinguishable)
Steel post 2' west
Post w/sign 2' north
This corner is located by GPS reference stations "End Road A & B"

Corner History:

1854 Gov't Notes M.G. Karrick, Deputy Surveyor West on true line between 9 and 16. 40.00 chs. Set a quarter section post. White Oak 14 in. N50°W 89 lks. White Oak 18" S47°W 113 lks.

5-1856 Thos. Hunter (Pg.5 No.8) shows 1/4 post. 1/16 North 19.79 M & L to center section.

1-1864 P.C. Compton (Pg.79 No.118) shows 1/4 cor. See survey for SE 1/4 NE 1/4 sec. 16.

9-1876 Thomas Hunter (P.305 No.300), County Surveyor, found stake standing which did not agree with witness trees. Dug and found part of original stake 2' west. Set an ironwood stake in its place.

9-1886 T. Hunter (P.415 No.404); found stake and tested witness trees and set stakes west.

11-1886 T. Hunter (P.417 No.406) found stake and set stakes south.

4-24-1972 County Surveyor, see center 16 for line of N-S 1/4 line. Ran on 50' offset West from 1/4 16-21 (final cor) over limestone at center 16 as now in place setting back to 40' in final setting of 2656 from stone and nail 125' North for elec meas North. The 2656 point proved 2618.6 to center 9 later found 4.65 or 2613.95 from North.

3-9-1973 County Surveyor ran traverse from 1/4 9-16 after running direct offset line (no traverse) from 1/4 4-9 at 555.13'. Cut back to 40' which after finding center 9 .45 West would actually be 40.0 at send corrected West to true line. Found old post stub with solid post stub in it at 36.7 West or 35.8 W and stake hole at 39.6 or 38.7 W at 12.7 South of 2656 (post stub dicounted as too far East).

4-25-1973 County Surveyor found a wood stake after much digging. Reset the corner on line from the north and used the wood stake found .9' east for north-south location

6-1974 County Surveyor visited corner since there was logging going on in the area. Found corner under a tree top.but monument o.k. RP's in place

11-25-2002 County Surveyor found CIM at surface leaning SE. Removed CIM found 1/2 iron rod down 2.1'. Set 4' Telspar w/CIC up 0.3'. Set 60d spike in West side of 24" white oak tree SSW 30.95' center of blazed 15" oak NNW 20.88'. Set sign & post and set steel post.