Certificate of Location of Government Corner

ID#:530905 **Description:** SEC COR 8 9 16 17 53 **Date Set:** 7/3/1975 **County:** Olmsted

Section: 09 **Township:** 105N **Range:** 13W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 1' west of CP for fences E-W-S
Spike in S side 20" Boxelder ESE 116.6'
County Survey Disk in E side 31" Oak SE 125.6'
Spike in W side 20" Oak S 104.1'
Sign on CP east 1'
This corner is located by GPS measurement

Corner History:

5-1854 Gov't Notes Michael Karrick, Deputy Surveyor North between sections 16 and 17. 80.00 chs. Set post for corner to Sections 8, 9, 16, 17. Dug trench. Black Oak 12 in. N35E 342 lks. Bur Oak 10 in. S68E 443 lks.

5-1856 Thomas Hunter (P.4 No. 7), County Surveyor, used corner. (pg5 No.8) used sec. cor. 1/16 North 19.91 chs. M & L to 1/4 post. 1/16 South 20.06 chs. M & L to 1/4 post.

9-1886 T. Hunter (P.415 No. 404), County Surveyor, found remains of old stake in road near corner of the fence. Set stone in place of stake.

11-1886 Thomas Hunter (P.417 No.406) found stone P.415.

4-1895 William Fraser (P.565 No.518), CountySurveyor, found stone P.415.

4-1895 William Fraser (P.565 No.518), County Surveyor, found stone P.415.

3-6-1973 County Surveyor ran traverse from 1 point to E 1/4 8, W 1/4 8, nail at 1/4 8-17 and 1/6 fence N and point near section corner SE 8 ground snow packed and frozen hard.

4-11 & 25-1973 County Surveyor found stone (down 6") on West side of corner post. Put irons around stone. RPs- 103.75 S to 20D nail west side center 28" oak, 116.4 ESE to 20D south side hugh boxelder, corner does line every well with fence east some 150' ± east.

7-3-1975 County Surveyor straightened stone and placed a flat iron on the South side. Set a CIM over all. RPs- Corner falls 1' west of corner post for fences E-W & south, Spike in S. Side 20" boxelder ESE 116.6, CS disc & spike on E side 31" oak SE 125.6, Spike in W. side 20" Oak S 104.1.

11-26-2002 County Surveyor found CIM at surface in good condition. Monument falls underneath E-W fence. Did not check ties.

11-19-2008 County Surveyor found CIM at surface in good condition.