Certificate of Location of Government Corner

ID#:531104 **Description:** 1/4 SEC COR 11 14 53 **Date Set:** 10/6/2003 **County:** Olmsted

Section: 11 **Township:** 105N **Range:** 13W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 50'± east of small stream and 250'± east of centerline of grass trail on east side of north edge of small pond
60d spike in S side 4" Aspen WSW 13.45'
60d spike in W side 20" twin Aspen NNE 16.73'
Post w/sign 3' west
This corner is located by GPS reference stations "B. Hinz A & B"

Corner History:

5-1854 Gov't Notes Michael Karrick, Deputy Surveyor West on true line between sections 11 and 14. 40.00 chs. Set quarter section post. Sugar 12 in. N5°W 45 lks. Sugar 12 in. S25°E 32 lks. 80.00 chs. To Section corner.

5-1885 Hunter (unrecorded survey in old fieldbook # 14 Page 38) used corner to run 1/4 line South and shows 1/16 East midway (20 chs) Property comes 10 chs South and 27.50 chs South then 40 chs to poplar stake, pitts at mound at center 14 (E-W 1/4 line not run) not clear that he actually had to set 1/16 East.

9-1893 William Fraser (P.532 No.495), County Surveyor, found a stone avered by a Mr. Campbell as set by him in the exact spot of the original corner stake.

1938 Archie Armstrong (County Highway Department Bk. 97 P. 15) found a limestone 3"x8" on top with an old stake on the East side of it. A Mr. Frank Campbell said his father set it where the original corner was located. Referenced the corner as follows: Corner lies 2' North of the E-W fence, a 10" elm in fence line East 22.8', and a 12" Elm SW 3.9'.

5-7-1949 Stone graded out. A 1" orange pipe was reset on the East backslope of the road from the remaining reference points.

4-29-1976 County Surveyor found an orange colored pipe on the steep sidehill along the old road. The pipe fit the old references to the fence line east and a large elm in the fence line East so accepted the pipe as the corner and left as found.

10-3-2003 County Surveyor found 1" orange pipe up 0.5' on steep slope East of small stream running through state land. Old road is gone and overgrown. Remnanats of any fence gone along with elms.

10-6-2003 County Surveyor removed 1"x3' orange pipe and set a 4' telspar with Cast Iron Cap up 0.2' from local ties. Set sign and post 3' West.