Certificate of Location of Government Corner

ID#:531205 **Description:** SEC COR 11 12 13 14 53 **Date Set:** 4/28/1977 **County:** Olmsted

Section: 12 **Township:** 105N **Range:** 13W **Monument Description:** Cast Iron Monument

Reference Ties:

SE corner of concrete block pump house NW 194.6'
Punch mark in top clamp S end 18" CMP N 142.95'
County Survey Disk in N side PP #40498 NE 165.23'
This corner is located by GPS reference stations "Gnats & Hawk"

Corner History:

1854 Gov't Notes Michael Karrick, Deputy Surveyor North between sections 13 and 14. 80.00 chs. Set post for corner to sections 11-12-13-14. Elm 13 in. S53W 21 lks. Elm 8 in. N48W 36 lks. Elm 15 in. N46E 52 lks. Elm 8 in. S56E 22 lks.

2-1874 Thomas Hunter, County Surveyor, (P.239 No.241) found the stake standing and the S.W. bearing tree as well as the stumps of the other bearing trees. Found the stake to be 20 lks. Too far West. Broke the stqke off and reset it in frozen ground. Then all bearing trees checked good.

5-1885 T. Hunter (unrecorded survey in old fieldbook #14 Page 38) shows 1/16 W midway (2. chs).

1-1893 William Fraser, County Surveyor, (P.504 No.474) used the corner to set 1/4 Cor. 11-12 midway and on line.

9-1893 William Fraser, County Surveyor, (P.532 No.495) could not find the stake driven P.504. Located the corner from the SE bearing tree and also the stump of one of the other bearing trees, and a Mr. Campbell said he would plant a stone.

5-1900 Robert Fraser, Deputy County Surveyor, found a stone set by William Fraser.

10-1938 A. Armstrong (County Highway Department B.97 P.14-17) set the corner on line with the fence from the West and at a distance of 2637.4' from 1/4 Cor. 11-14 which he states: "is the distance given in survey by William Fraser 1893 on Page 532 Book A". Dug considerably at this spot but found nothing. This point is very close to the spot a Mr. Campbell and a Mr. Nesbit said the corner should be. Set a 3/4"x15" pipe. Note: Fraser's measure of 2637.4' was from Section Cor. 10-11-14-15 to 1/4 cor. 11-14 and not from 1/4 Cor. 11-14 to Section Cor. 11-12-13-14.

5-1949 Ken McGhie, a surveyor, found a 3/4" pipe. RPs-SE corner barn foundation WNW 192.5, corner fence post SSE 95.4, 12" walnut NNW 179.3, spike 16" stump SW 50.8.

4-25-1975 County Surveyor found a 3/4" pipe. RPs- punch mark in top clamp of south end 18" driveway culv. N 145.85', CS Disc in N side PP #40498 NE 165.23'

4-28-1977 County Surveyor set a CIM over a 1/2"x2' rod as the corner on line from 1/4 cor. 11-14 over a corner post found at the 1/16th East and midway between 1/4 Cor. 11-14 and 1/4 Cor. 12-13. This corner is 4.41' North and 9.12' West of Armstrong's corner (removed). RPs-SE corner of concrete block pump house N.W. 194.6', Punch mark in top clamp South end 18" C.M.P. north 142.95', C.S.D. in north side PP #40498 NE 165.23'.

10-04-2004 County Surveyor found CIM down 1.6' in good condition.