Certificate of Location of Government Corner

ID#:531206 **Description:** 1/4 SEC COR 11 12 53 **Date Set:** 8/3/2011 **County:** Olmsted

Section: 12 **Township:** 105N **Range:** 13W **Monument Description:** Cast iron cap on telspar pipe

Reference Ties:

The monument is up 0.3'
The monument falls 10' north of east-west fence.
Post with sign 2' west
This corner is located by GPS reference stations "Pearson C & D"

Corner History:

1854 Gov't Notes M.G. Karrick 40.00 set 1/4 section post White Oak 13 S 35 E 35. White Oak 15 W 24 W 50.

1-1893 W. Fraser (P504 No.474) corner gone, no evidence or knowledge what so ever set marked stake M & L BT M 45°W 4 links. South set corners 14.86 7/8 then 4.95 5/8 to 1/16 corner then 9.91 1/4 then 9.91 1/4 to SW 12. (not descrbed but used). Meas North 19.82 1/2 to 1/16 corner then 3.47 7/8 229.59 then 16.34 5/8 to NW 12 a stone. East set corners on indifinate assumed line.

5-4-1976 County Surveyor will set corner at intersection of fence line from W and line from sec cor 1-2-11-12 to sec cor 11-12-13-14. RP's to traverse nail: 1st steel post in fence W SW 16.32. Red Head E side of the tree where fence from W turns S S. 11.35.

3-8-1977 McGhie & Betts set pipe w/cap at County Surveyor location on line between section corners and in line of fence west.

7-12-1983 McGhie & Betts found and used pipe w/cap in survey of section 11.

10-4-1994 McGhie & Betts found and used pipe w/cap in survey of section 11.

10-7-2003 County Surveyor visited area of corner. Found nothing.

11-1-2004 County Surveyor found 5/8" pipe w/plastic cap broken in good condition.

8-3-2011 County survey crew found 5/8" pipe in good condition. Removed and replaced with a 2' telspar pipe with cast iron cap