Certificate of Location of Government Corner

ID#:531304 **Description:** 1/4 SEC COR 13 24 53 **Date Set:** 10/7/2004 **County:** Olmsted

Section: 13 **Township:** 105N **Range:** 13W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls in centerline of N-S twp road and in line with fence west
County Survey Disk in SE side PP SW 53.60'
County Survey Disk in N side RR tie CP W 32.81'
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes M.G. Karrick East Random 13 & 24. 40.00 set temp section post West on true line between section 13 & 24. 40.05 set 1/4 section post N 10° 31'. Hickory 10 N 70 E 25. White Oak 10 S 30 E 42.

1-1872 T. Hunter Pg.190 No.201; Corner gone. Reset from stumps of bearing trees with marks plain.

2-1874 T. Hunter Pg.239 No.241; Found stake. Tested bearing tree stumps. Set stake at 1/16 north, found 1/16 east, 1/16 west set stake, 1/16 south found stake.

T. Hunter replaced stake from brg tree in 1872 and stake used again by T. Hunter in 1874 and 1885. No record of when stone was set but limestone (4"x8"top) with iron drag tooth was found by Co. Hwy. Dept. in 1938 and their ties were used to locate at this time.

1-1894 W. Fraser (P541 No.502) SW 1/4 13 woodlots found marked stake (P403) and bearing tree. 1/16 West found stone stake by side (P403). 1/16 North set stake M & L 19.81 1/2 set stakes North 7.92 + then 4.95 + to 1/16 North 1/4 13-24. Set oak block with stake by side at intersecting lines of E-W 1/4 line and a N-S line East of center sec 13 17.50 chs West of SE 13 and 17.60 1/2 chs West of NE 13 land through center on N-S 1/4 line rough.

1938 county highway department Bk.96 Pg.1; Found limestone & drag tooth 12" deep. RPs- twin elm E 22.3, 24" basswood SE 56.1, corner fence post NW 35.7.

1965 county highway department Bk.307; Found hub set in 1938. Put 60D spike in hub. RPs- disc in pp SW 51.89, disc in tele pole SSE 89.14, disc top cor post NE 56.76, disc in fence post W 16.9.

6-25-1970 County Surveyor found limestone and drag tooth and placed a cast iron monu. over stone. RPs- old disc in pp# 16404 SW 51.88, old disc in fence post W 16.76, old disc in tele pole SSE 89.16, corner lies in center old 2 rod trail running north in fair line very old fence west.

10-6-2004 County Surveyor found CIM with head broken off down 0.1'

10-7-2004 County Surveyor removed CIM, found stone with drag tooth on west side and removed. Set 5' telspar with CIC down 0.5' driven to refusal from ties taken from CIM, stone matched.

1-16-2008 County Surveyor found cast iron cap on telspar pipe down 0.7' in good condition.