Certificate of Location of Government Corner

ID#:531305 **Description:** SEC COR 13 14 23 24 53 **Date Set:** 6/25/1970 **County:** Olmsted

Section: 13 **Township:** 105N **Range:** 13W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls in line with centerline of twp road east, 8 1/2' east of centerline of twp road north and 19' SW of centerline of twp road on curve
Post w/sign 20' south
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes M.G. Karrick. 80.00 set post for corner to section 13,14,23 & 24. White Oak 8 S 55 W 40. White Oak 9 N 48 W 24. White Oak 7 N 35 E 42. White Oak 8 S 50 E 58.

2-1870 R. Perry (P.102 No.142) reset stake from all bearing trees standing and checking correct except SW B.T. which should be 44 links instead of 40 links. Meas South 39.96 meas West 40.13.

Above found limestone was set by W. Fraser in 1895 in place of a stake found by T. Hunter in 1874.

9-1885 T. Hunter (P.403 No.392) J. Baker, G. Lowrie found stake (P239) tested B trees, found SW B.T. J. French off 4 links. 1/16 East found stake M & L 19.98 (P.265). Meas South 40.00 with temp stake set M & L.

1-1894 W. Fraser (P541 No.502) found hole where stake stood, tested stump NE B.T. replaced stake. 1/16 North set stone 5 x 8 x 15 M & L 19.85 N 1°30 W. 1/16 East found stone and stake set by Hunter survey sec 24.

4-1895 W. Fraser (P563 No.517) found stake set (P.541) stone 4 x 5 x 22. Found 1/16 stakes West-South and center NE 1/4. Set new stakes B trees also.

1938 county highway department found stone. RPs- steel cor. Fence post S 33', cor. Fence post NE 27.9, spike in 2nd fence post W 36.4. Avered by Mr. R Yates.

6-25-1970 County Surveyor found stone 4 x 5 x 21 with 1" x 24" re bar on South side of stone. Set C.I.M. over re bar with orig stone on N side of C.I.M., glass trash etc. Beer bottle cap on W side PP# 16393 SE 23.3. Hole on West side 3" ± steel corner post in conc. S. 33.18. Pepsi cap in edge RR tie (NW edge) NE 33.68. Corner lies .8' East of fence South. 1/16 East found old grate, set pipe riser (see 1/4 13-24).

9-10-2001 County Surveyor found CIM down 1.3' in good condition in Southerly ditch of twp road on curve.

12-7-2001 County Surveyor tied out corner for possible road/ditch work.

10-6-2004 County Surveyor found CIM in good condition down 1.4'.

1-7-2008 County Surveyor found CIM down 1.4' in good condition.