Certificate of Location of Government Corner

ID#:531405 **Description:** SEC COR 14 15 22 23 53 **Date Set:** 8/17/1982 **County:** Olmsted

Section: 14 **Township:** 105N **Range:** 13W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 1' NE of CP to fences E-W-S
Sign on CP 1' SW
This corner is located by GPS measurement

Corner History:

5-1854 Gov't Notes Michael Karrick, Deputy Surveyor North between Sections 22 and 23. 80.00 chs. Set post for corner to Sections 14, 15, 22, 23. Jack Oak 8 inch N50°E 470 lks. Dug trench.

7-1856 W.H. Mills, Surveyor, (Old Road Book, Road No. 29) surveyed a road running South and NW here but makes no call for the corner.

6-1&2-1886 Thomas Hunter, County Surveyor, (Book A, Page 410, No. 399, and Old Fieldbook 14, Page 63, and Old Fieldbook 14, Page 67) "This corner was also missing and the witness tree cut and gone and unrecognizable. But Mr. John Clark, an old settler who owns land on the West side of said corner both North and South of it claims that until a few years since the original stake stood about one foot East of the corner post of his fence running west as he built his fence runnign N&S one foot on himself, and Mr. J. O'Connal agreeing with Mr. Clark as to it being about a foot East of the N&S fence but he thinks it was opposite a post in said N&S fence, about four feet South of Clark's fence running West but as Clark was positive he started his E&W fence from the corner when he built we accepted his statement, giving Mr. O'Connell the benefit of the doubt as to who is correct. We therefore assumed a point one foot East of corner post of John Clarks fence running West as the corner but we set no stake or corner of any kind." He used this corner to set 1/4 Cor. 15-22 (no description) midway (40.09 chs.) and on line to the SW Cor. 15.

1-1894 William Fraser, Deputy County Surveyor, (Book A, Page 543, No. 504) "Found remains of old post at corner in line of old fence running West as spoken of in Survey 399 and planted stone 26x12x2, just 1 foot East of post, as that was the point given by Hunter where the Gov't corner stood." He used the corner to set stakes at the 1/64 North, the 1/16 North, and the 1/64 North of the 1/16 North (measure North 39.76 chs.).

4-1895 William Fraser, County Surveyor, (Book A, Page 563, No. 517) "Found stone as set by me in Survey 504, Page 543 this Book." He used the corner to set 1/4 Cor. 22-23, a stone and iron stake, midway (39.88 chs.) and on line to Sec. Cor. 22-23-26-27, a 15x4x4 inch stone set this survey. Also set the 1/16 South of 1/4 Cor. 22-23, a stone and stake, midway (19.94 chs.) and on line to Sec. Cor. 22-23-26-27.

2-1896 William Fraser (Book A, Page 591, No. 537) found corner as set in survey No. 517, page 563. He used the corner to set the 1/16 South, a stake not marked, midway (19.94-1/2 chs.) and on line to 1/4 cor. 22-23 (found corner set Page 563).

5-15-1972 County Surveyor dug at the corner post to fences E-W-S. Found a 12"x1"x2" iron and glass; however, the iron was not standing vertical and we could not find Fraser's stone. Found a very old post stub down 2' in clay on the North side of the corner post in place. Accepted this as the old post used by Fraser and set a steel fence post on the East side as a temporary corner as recorded by Fraser. Measured 2619.8 North to 1/4 Cor. 14-15 as set this survey.

2-1981 Dave Knutson & Jerry Schwarz found u-shaped steel post as corner.

8-17-1982 County Surveyor set a square pipe (telspar) with a Cast Iron Cap in place of the steel fence post set 5-16-1972. Measured 2644.33 West to Cast Iron Monument over stone found in 1972. Measured 2633.47 south to 1/4 Cor. 22-23 set this survey at the intersection of the line from the W. 1/4 cor. 22 (CIM where cedar stake found in 1972) over the Center 22 (pipe over iron pin found in 1972) and the line from the SE Cor. 22 (CIM over Fraser's stone found in 1972) and the NE Cor. 22 as set this susrvey. In 1972 we also found Fraser's stone and stake at the 1/16 South of 1/4 Cor. 22-23 which falls just .24 East of the section line as established by our electronic traverse comp.

1-8-2003 County Surveyor found telspar w/CIC in good condition up 0.4'.

10-11-2004 County Surveyor found cast iron cap on telspar pipe up 0.4' in good condition.